

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 24.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Gopalpet	33KV	Wanaparthi	13.15	15.40	02.25	E/L&O/L	Due to LV's Pul Out Alternate Supply Arranged form 33KV RevallySS at 15:40Hrs	Gopalpet	for Alternate supply Arranged form 33KV RevallySS at 15:40Hrs

TSSPDCL - LMRC / Corporate office

Date: 24.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kethepally	Korlapahad	11KV	Nalgonda	09.30	11.40	02.10	E/L	11KV Line Insulator failure	-
2		Pullemla	Kondapuram	11KV	Nalgonda	14.48	16.50	02.02	E/L	Jumper cut	-
3		Rajavaram	JC Thanda	11KV	Miryalaguda	09.56	11.02	01.06	E/L	Line cut	-
4		Dilchincerla	Chilepally	11KV	Huzurnagar	12.30	14.05	01.35	E/L	Line cut	-
5		Keethavarigudem	Sarvaram	11KV	Huzurnagar	15.40	16.45	01.05	E/L	Jumper cut	-
1	RR N	Kolthur	Kolthur	11KV	Medchal	10.05	11.35	01.30		11KV Pin Insulator failed at Bagi Reddy Thota Kolthur	-