

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	2		2		2				
	Total	606	3055	2	1	2	1	2	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		5		5		5			
3	MDK	107	933		1		1		1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	3	8	3	8	3	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Gopalpet	33KV	Wanaparthy	20.20	22.10	01.50		Conductor Twisted at Eidga	Gopalpet	-
1	HYD N	132KV Gunrock	Hakimpet	33KV	Bowenpally	00.12	00.18	00.06	OL-Rph	Old Straight through Joint failed at Muthyalamma Temple	Hakimpet	Loads transferred onto 132KV Gunrock SS via 33KV R.P Nilayam fdr
2		132KV Jubilee Hills	Sundew (HT service)	33KV	Jubilee Hills	17.41	18.05	00.24	EL,OL-R,Y&Bph	Cable damaged by Master Plan wing at Durgam Cheruvu	Sundew (HT service)	Loads transferred onto 132KV Madhapur SS via 33KV Intime Properties fdr

TSSPDCL - LMRC / Corporate office

Date: 28.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thatipamula	Nandhapuram	11KV	Suryapet	09.30	11.50	02.20	E/L	11Kv Insulator failed	-
2		Gaddipaly	Medaram	11KV	Huzurnagar	03.00	05.45	02.45	E/L	11Kv line snapped	-
3		Gondriyala	Gondriyala 02	11KV	Huzurnagar	05.10	08.00	02.50	E/L	11Kv line snapped	-
4		Gondriyala	Chimiryala	11KV	Huzurnagar	06.10	09.05	02.55	E/L	11Kv line snapped	-
5		Juloor	Kapraipally	11KV	Choutuppal	10.55	13.10	03.15	E/L	Single Phase DTR Fail In Kapraipally Village	-
1	MDK	Narsapur	Hathnoora	11KV	Town Ind	16.30	17.30	01.00		B/D due to Conductor snapped	-
2	SDPT	Gandipally	Nandaram	11KV	Husnabad	09.10	09.40	00.30		S-Ph DTR jumper cut same rectified	-
1	RR E	Nacharam Indore	Ram Reddy Nagar	11KV	Habsiguda	18.10	19.20	01.10		11KV Cable incoming jumper cut in Srinivasa Apartment at Savarkar Nagar	-