

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	11	3	11	3	11			
2	NLG	144	988	1	11	1	11	1	11			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	24	6	24	6	24	0	0	
	Grand Total	1082	6468	6	31	6	31	6	31	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanpur	Lattupally	33KV	Wanaparthi	14.18	16.46	02.28	E/L	AB Switch Open at Manganoor & Lattupally	Ghanpur	No
2		Nagarkurnool	Manthathi	33KV	Nagarkurnool	15.45	11.10	19.25	E/L	Replacment of 33KV Insulator at Manthathi village	Nagarkurnool	NO
3		Singotam	Narsaipally	33KV	Nagarkurnool	11.59	13.06	01.07	E/L	Failure LA Replacement near Mahasamudram	Singotam	NO
1	NLG	Kolanpaka	Suddala	33KV	Bhongir	12.35	16.20	03.45	EL	Tree Branchess Fallen at Line Near Koanpaka 132 KV Sub station		-
1	MDK	Zaheerabad	Old Allana	33KV	Zaheerabad	14.25	18.00	03.35		B/D Due to Jumper Cut and Insulator Failure		-
2		Zaheerabad	Mirzapur	33KV	Zaheerabad	14.25	15.25	01.00		B/D Due to Jumper Cut		-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Waddeman	Nellikondi	11KV	Mahabubnagar	18.10	21.15	03.05		11KV pole damage at Waddeman (Vi) 1	-
2		Perur	Venkampally	11KV	Mahabubnagar	06.50	11.05	04.15		11KV Tree fallen on conductor at Venkampally (Vi)	-
3		Kokuntla	Gopanpally	11KV	Mahabubnagar	10.00	12.50	02.50		11KV Tree fallen on conductor Near Gopanpally & pole damage (Vi) 4	-
4		Baswaipally	Laxmipally	11KV	Mahabubnagar	08.00	11.00	03.00		11KV Tree fallen on conductor Near Laxmipally & pole damage (Vi) 2	-
5		Baswaipally	Chowderpally	11KV	Mahabubnagar	17.00	20.20	03.20		11KV pole damage at Chowderpally (Vi) 3	-
6		Waddeman	Waddeman	11KV	Mahabubnagar	18.10	20.00	01.50		11KV pole damage at Waddeman (Vi) 1	-
7		Marikal	Malkapur	11KV	Jadcherla	12.18	14.04	01.46		B.D. 11Line Cut Near Malkapur(Vi).	
8		Karvena	Kothur	11KV	Jadcherla	07.50	08.52	01.02		B.D. 11 Kv Insulator Failure Near Aloor Tanda Side.	
9		Midjil	Munnanoor	11KV	Jadcherla	12.35	13.10	00.35		B.D. 11Kv jumper Cut Near Munnanoor(Vi).	-
10		Marikal	Malkapur	11KV	Jadcherla	12.18	14.04	01.46		B.D. 11Line Cut Near Malkapur(Vi).	-
11		kothamolgara	Karvena	11KV	Jadcherla	23.15	07.40	08.25		B.D.11Kv insulator bust And 11Kv conductor Cut Near Soula Tanda Side.	-
1	NLG	Mushampally	Muthyalamma	11KV	Nalgonda	07.30	09.30	02.00	EL	Jumper cut	-
2		Kethepally	Korlapahad	11KV	Nalgonda	07.12	11.38	04.26	EL	11 KV Line cut and HT/LT line milting	-
3		K.M.Pally	Chennaram	11KV	Devarakonda	05.00	06.30	01.30	EL	Tree Fallon	-
4		Chinthapally	Vinjamoor	11KV	Devarakonda	06.00	13.11	07.11	EL	Jumper Cutt & 1Nos insulatotr failed	-
5		Madanapuram	Madanapuram	11KV	Devarakonda	06.00	11.30	05.30	EL	3Nos 11KV Disc & 2Nos Pin Insulators Failed	-
6		Teeded	K.Gowraram	11KV	Devarakonda	06.00	07.00	01.00	EL	Tree Fallon	
7		Marriguda	Y.G.Pally	11KV	Devarakonda	05.00	09.00	04.00	EL	4Nos 11KV Insulator failed	
8		Chandupatla	Kunoor	11KV	Bhongir	06.45	09.55	03.10	EL	HT/LT Near Kesaram Village.Single	-
9		Wangapally	Choller	11KV	Bhongir	03.15	07.00	03.45	EL	2no's DP Poles Dammages near Challur Village	-
10		Peddaravlapally	Indriyala	11KV	Choutuppal	18.40	07.10	12.30	EL	9no's LT Poles & 3no's 11kv Poles Dammaged Near Indriyala Village	-
11		Peddaravlapally	Gousekonda	11KV	Choutuppal	18.40	21.30	02.50	EL	2no's LT poles Dammages near Gouse konda Village	-
1	MDK	Kistareddypet	Industrial	11KV	Patancheru	01.00	01.45	00.45		B/D Due to Insulator Failure	-
1	SDPT	Marmamula	Dharmaram	11KV	Husnabad	07.50	09.10	01.20		BD,Insulator failure	-
1	RR S	Gaganpahad	NPA(GPHD)	11KV	RJNR	13.15	14.18	01.03	B/D	11KV Insulator failed at Tamilanadu hotel Opp	-
1	RR N	Medchal	IDA Kistapur	11KV	Medchal	17.15	18.40	01.25	BD	11KV Line cut & replacement at Kistapur road	-
1	RR E	Anandbagh	NMDC	11KV	Sainikpuri	06.02	07.05	01.03		Tree branches fallen on 11Kv line at Bank Colony East Anandbagh (Artisan Ranga Reddy)	-
1	HYD N	Macha Bollaram	Father Balaiah Nagar	11KV	Bowenpally	16.30	17.40	01.10	OL-Bph	Conductor snapped at Bhoo Laxmi Temple	-
1	HYD S	Miramam	Shaik-E-Masjid	11KV	Charminar	17.14	18.40	01.26	EL,OL	End Kit failed at OYC Hills	-
1	HYD C	Indirapark	Air Force-II	11KV	Saifabad	07.19	09.19	02.00	OL-Bph	No Visible Fault	-
2		Lumbini Park	A.P Tourism	11KV	Saifabad	12.57	14.35	01.38	EL,OL	Cable Burnt out at I.C.Quarters	13:18 Hrs partial fdr charged