

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	3	33	3	33	3	33			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>34</b>	<b>4</b>	<b>34</b>	<b>4</b>	<b>34</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>40</b>	<b>4</b>	<b>40</b>	<b>4</b>	<b>40</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 02.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Narayanapet	18.55	20.20	01.25	O/L	33KV Krishna feeder loads tag on to 33KV Gudeballore feeder at 20:20Hrs ( Due to 33KV Line Fault )	Krishna	-
1	NLG	Marriguda	Gattuppal	33KV	Nalgonda	19.30	11.20	15.50	EL	2Nos. 33KV insulators failed	Gattuppal	-
2		K.M.Pally	SLBC	33KV	Devarakonda	19.00	07.50	12.50	EL	33 KV 1No Insulator Failed	SLBC	-
3		Ramapuram	Thogarrai	33KV	Huzurnagar	03.00	07.30	04.30	EL/OL	33 KV LINE SNAPPED	Thogarrai	-

## TSSPDCL - LMRC / Corporate office

Date: 02.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
1	NLG	Gattuppal	Lachammagudem	11KV	Nalgonda	08.27	12.30	04.03	E/L	11KV Jumper cut	-	
2		Akaram	Vaddipamula	11KV	Nalgonda	10.00	14.00	04.00	E/L	HT/LT line melting at SS-14		
3		Narsingbatla	Chennugudem	11KV	Nalgonda	09.50	11.25	01.35	E/L	11KV Jumper cut		
4		Thummdam	Nethapuram	11KV	Miryalaguda	07.45	12.00	04.15	E/L	Tree fallen on the line		
5		Thummdam	Thummdam	11KV	Miryalaguda	08.40	10.20	01.40	E/L	11KV Disc insulator failed		
6		Settiapalem	Settiapalem -I	11KV	Miryalaguda	11.50	15.50	04.00	E/L	11Pin insulator failed near SS		
7		Thimmapuram	Kallepally	11KV	Miryalaguda	03.15	06.15	03.00	E/L	Tree fallen on the line		
8		Damarcherla	Damarcherla	11KV	Miryalaguda	03.45	06.30	02.45	E/L	11KV Disc insulator failed near village		
9		B.B.Gudem	Thimmareddy gudem	11KV	Miryalaguda	14.00	16.40	02.40			11KV Jumper cut at SS	
10		Devarakonda	Thurupupally	11KV	Devarakonda	06.00	09.00	03.00	O/L	HT/HT		
11		Chandampeta	Pollepally	11KV	Devarakonda	06.00	10.00	04.00	E/L	Conductor Snapped		
12		Dindi	Thirumalagiri	11KV	Devarakonda	06.15	13.10	06.55	E/L	HT/HT		
13		Yararam	Kamapally	11KV	Devarakonda	06.00	10.10	04.10	O/L	Jumper Cutt		
14		Cherukupally	Dindi rural	11KV	Devarakonda	09.00	13.30	04.30	E/L	11 kv Jumper Cu		
15		Teldevarapally	Teldevarapally	11KV	Devarakonda	05.30	08.30	03.00	O/L	HT/HT		
16		Angadipeta	Akkampally	11KV	Devarakonda	08.00	11.50	03.50	E/L	Snapped Conductor		
17		Gurrapode	Chepur	11KV	Devarakonda	02.00	10.00	08.00	E/L	11kv Disc Failed		
18		Pittalagudam	Vattikod	11KV	Devarakonda	04.55	06.50	01.55	E/L	Jumper Cutt		
19		Palvai	M.K.Gudam	11KV	Devarakonda	06.10	09.30	03.20	E/L	Jumper Cut		
20		T.P.Gouraram	S.Lingotam	11KV	Devarakonda	06.00	12.11	06.11	E/L	11Kv Snapped Conductir		
21		Marrigudam	T.M.Pally	11KV	Devarakonda	05.00	12.00	07.00	E/L	11kv Sanppend Conductor		
22		Athmakur(S)	T.Penpahad	11KV	Suryapet	03.30	06.20	02.50	E/L	Conductor snapped		
23		Palakeedu	G G Palem	11KV	Huzurnagar	04.00	06.30	02.30	EL	11 KV Jumper cut		
24		Huzurnagar	Burugadda	11KV	Huzurnagar	05.00	08.30	03.30	EL	11 KV INSLATER FAILED		
25		Mattampally	Allipuram	11KV	Huzurnagar	05.00	07.00	02.00	EL	11 KV Line snapped		
26		Kistapuram	Tammaram	11KV	Huzurnagar	07.00	09.30	02.30	EL	11 KV Line snapped		
27		IDA	Bommaipally	11KV	Bhongiri	08.10	11.05	02.55	OL	11 kv Line Snapped at Seethanagar Near Bhongir Town		
28		Peddathanda	Peddathanda	11KV	Bhongiri	06.00	09.30	03.30	OL	DTR Brass Patti cut Near Rusthapur Village		
29		Alair	Chinna kandukur	11KV	Bhongiri	11.00	13.25	02.25	EL	11 kv Jumper cut Near Ch.Kandukur Village		
30		Motakondur	Motakondur	11KV	Bhongiri	11.45	12.45	01.00	EL	11 kv Disc Failed at Durgamma temple Near Motakondur Village		
31		Choutuppal	Thangedipally	11KV	Choutuppal	14.30	17.30	03.00	EL	11 kv Jumper cut Near Chinthlagudem Village		
32		S.Lingotam	Lingojigudem	11KV	Choutuppal	07.08	13.42	06.34	OL	11 kv Line Snapped Near Lingojigudem Village		
33		Voligonda	Lothukunta	11KV	Choutuppal	09.15	12.30	03.15	EL	11 kv Jumper cut Near Lothukunta Village		
1	SDPT	Ramchandrapur	Vinjabally	11KV	SDPT	11.05	12.50	01.45		Tree branch fallen on line same rectified	-	
1	RR S	MD Pally	MD Pally (V)	11KV	RJNR	16.05	17.15	01.10	B/D	11kv Insulator Failed at pragathi colony government school	-	
1	RR N	Ravalkole	Cheruvukatta	11KV	Medchal	09.18	11.27	02.09		11KV Line Cut & Replaced at Madhava Reddy Thota T/F Backside	-	
1	RR E	Moula ali	Kailasagiri	11KV	Sainikpuri	20.48	21.20	00.32		T/F Ab switch sparking at Bakshiguda (Artisian Arif)	-	
2		Rampally	Venneguda	11KV	Keesara	09.45	10.45	01.00		11KV jumper cut at Holi marry collage	-	
1	HYD C	Golconda	Q.Q.Toombs	11KV	Mehdipatnam	09.47	11.03	01.16	OL-Rph	Phase sequence problem at Mini Gulshan Colony		
2	HYD N	Yellareddyguda	Savera	11KV	Erragadda	17.36	18.55	01.19	OL-Rph	No Visible Fault		