

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		16		16		16			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>19</b>	<b>1</b>	<b>19</b>	<b>1</b>	<b>19</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 03.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	R.C.Puram	ASHOK NAGAR	33kv	Patancheru	09.20	11.55	02.35		BD due to Insulator failed at Bheeranguda Common	ASHOK NAGAR	-

## TSSPDCL - LMRC / Corporate office

Date: 03.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Alingapuram	Raghavapuram	11kv	Huzurnagar	09.15	10.40	01.30	E/L	11Kv Jumper Cut	-
2		Kalmalcheruvu	Kalmalcheruvu	11kv	Huzurnagar	07.56	11.00	03.04	E/L	11Kv Jumper Cut	
3		Tekumatla	Yendlapally	11kv	Suryapet	07.10	09.20	02.10	E/L	11Kv Conductor snapped	
4		Alair	Ikurthi	11kv	Bhongir	10.00	11.45	01.45	EL	11 kv Pin Insulator Failed Near Dilvarpur Village.	
5		Peddathanda	Peddathanda	11kv	Bhongir	08.30	10.45	02.15	OL	DTR Copper Patti cut Near Maisamma kunta. Peddathanda Village.	
6		Azeempet	Kanchanapally	11kv	Bhongir	13.40	17.50	04.10	OL	HT/LT at SS - 2 Near Sadashapuram Village	
7		Suddala	Pallepahad	11kv	Bhongir	12.15	13.05	01.05	OL	HT/LT Near Pallepahad Village	
8		Choutuppal	Jublakpally	11kv	Choutuppal	13.45	17.50	04.05	E/L	Tree Branchess Fallen at Line Near Lingareddygudem	
9		Agamothkur	Bommakal	11kv	Miryalguda	08.40	10.20	01.40	E/L	11KV Disc insulator failed	
10		Settiapalem	Settiapalem -I	11kv	Miryalguda	11.50	15.50	04.00	E/L	11Pin insulater failed near SS	
11		Utlapally	Yadgiri Pally	11kv	Miryalguda	01.54	07.00	05.06	E/L	Tree fallen on the line	
12		Damarcherla	Vadapally	11kv	Miryalguda	10.16	10.45	00.29	E/L	Insulator failure	
13		B.B.Gudem	Pamula padu	11kv	Miryalguda	10.10	12.00	01.50	E/L	11KV Jumper cut at SS	
14		Rjavaram	Rjavaram	11kv	Miryalguda	09.40	09.50	00.10	E/L	Insulator failed	-
15		Velugupally	A.R.Guda	11kv	Nalgonda	09.20	11.30	02.10	E/L	11KV Line Jumper Cut	-
16		Rayanguda	Gaddikondaram	11kv	Nalgonda	13.40	15.00	01.20	E/L	11KV Line Disc Failur	-
1	RR N	UMCC	RM Nagar	11kv	Medchal	03.10	04.00	00.50		No Fault	-
2		Devarayamjal	DMC	11kv	Medchal	07.30	09.30	02.00		11KV Jumper cut and replaced at Etela Rajender Godown	-
1	HYD S	Gosha Mahal	M.J.Market	11kv	Begumbazar	10.58	12.14	01.16	EL	Cable fault	Arranged B/F on 11KV Osmangunj ndr