

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933									
4	SDPT				8		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	14	2	14	2	14	0	0	
	Grand Total	1082	6468	2	14	2	14	2	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shantinagar-1	33KV	Gadwal	13.44	15.20	01.36	E/L	AB Switch opened at Paipad Stage		Alternate Supply Arranged from Shantinagar-2 at 15:20Hrs
1	NLG	Nalgonda	Pazzur	33KV	Nalgonda	05.45	08.55	03.10		Tree Branches On The Line		-

TSSPDCL - LMRC / Corporate office

Date: 07.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	B Chandupatla	Bimlathanda	11KV	Suryapet	13.15	16.00	02.45	EL	Disc failed	-
2		Keethavarigudem	Sarvaram	11KV	Huzurnagar	12.20	13.20	01.00	EL	11 KV LINE SNAPPED	-
3		Raghunadapalem	Gundlapally	11KV	Huzurnagar	09.00	11.00	02.00	EL	11 KV INSLATER FAILED	-
4		Palem	Ogodu	11KV	Nalgonda	13.05	15.30	02.25	EL	HT/LT Melting	-
5		Aregudem	Pedda Kaparthy	11KV	Nalgonda	06.45	11.38	04.53	EL	11KV Line Disk and Insulator Failur	-
6		Bollepally	Bollepally	11KV	Bhongir	14.30	16.40	02.10	EL	11 kv Insulator Failed Near Bollepally Village.	-
1	SDPT	Baswapur	Muthannapet	11KV	Husnabad	14.55	16.45	01.50		BD,Jumper cut	-
2		Gurjakunta	Dommata	11KV	Husnabad	13.00	17.00	04.00		BD,Conductor snapped	-
3		Dharmaram	Dharmaram(R.)	11KV	Husnabad	13.00	17.05	04.05		BD,Jumper cut	-
4		Husnabad	Malapally	11KV	Husnabad	14.25	23.10	08.45		BD,Tree fallen on line & conductor snapped	-
5		Ramchandrapur	Varikolu	11KV	Husnabad	20.40	21.30	00.50		BD,Cable cut	-
6		Gagillapur	Narsaipally	11KV	Husnabad	14.50	15.43	00.53		BD,Tree fallen on line	-
7		Rebarthy	Ladnoor	11KV	Husnabad	15.25	23.00	07.35		BD,Jumper cut	-
8		Rebarthy	Rebarthy	11KV	Husnabad	09.50	10.50	01.00		BD,Conductor snapped	-