

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	14	0	14	0	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Velugupally	Keshavapuram	11KV	Suryapet	15.45	18.00	02.15	EL	Insulator failed	-
2		Narketpally	Mandra	11KV	Nalgonda	11.50	13.30	01.40	EL	11KV Line Jumper Cutting	-
3		Thipparthi	Marriguda	11KV	Nalgonda	09.20	11.05	02.05	EL	AB Switch Jumper Cutting	-
4		Gudapur	Sanabanda	11KV	Nalgonda	10.00	12.10	02.10	EL	11KV Line Insulator Failur	-
5		Ponugodu	Kothagudem	11KV	Huzurnagar	06.08	07.50	01.42	EL	11kv Snapped	-
1	SDPT	Potharam	Keshavapur	11KV	Husnabad	13.40	18.30	05.40		Heavy Gail and wind	-
2		Husnabad	Malapally	11KV	Husnabad	00.00	09.30	09.30		Line cut	-
3		Begumpet	Laxmipur	11KV	Husnabad	11.30	13.15	01.45		Heavy Gail and wind	-
1	RR S	Kismathpur	Rock Church	11KV	RJNR	22.27	01.07	02.40	B/D	11kv Jumper Touching To Channel at NRI Township kismathpur	-
1	RR N	Madinaguda	Pragathi Enclave	11KV	Kukatpally	09.14	10.27	01.13	BD	HT Cable Failure Near RV Nirman at Pragathi Enclave	-
2		Subhash Nagar	Suchitra	11KV	Medchal	14.05	14.50	00.45	BD	Tree Branches fallen on the 11KV Line at Sarvottam Backside	-
3		GP Pally	GP Pally	11KV	Medchal	10.25	11.40	01.15	BD	11KV Line Touched to Box Pole at Aparna Gate	-
1	RR E	Vinayak Nagar	Tank Bund	11KV	Sainikpuri	08.05	08.25	00.20		11Kv Cable cut at Tank Bund (Artisian Sri Ramulu)	-
2		Rampally Dayara	Vanneguda AGL	11KV	Keesara	09.10	10.54	01.44		100KVA DTR Brass patti cut at Parsiguda Village	-