

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	2	2	2	2	2			
2	NLG	144	988		4		4		4			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 13.05.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Dharoor	33KV	Gadwal	18.30	20.40	02.10	EL	Top Phase insulator bend touched to crassarm	Dharoor	No
2		leeza	Venkatapuram	33KV	Gadwal	10.14	11.08	00.54	EL	No Visible fault	Venkatapuram	No

## TSSPDCL - LMRC / Corporate office

Date: 13.05.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	Moosapet	11KV	Jadcherla	11.40	12.41	01.01		11Kv Wire Cut Near Moosapet( Vi)Side.	No
2		Midjil	Boinpally	11KV	Jadcherla	07.00	11.00	04.00		11Kv Wire Cut Near Mallapur( Vi)Side.	No
1	NLG	Athmakrur(S)	Gotti mukkula gudem	11KV	Suryapet	8:00	10:15	2:15	E/L	Conductor snapped	No
2		Dirsenapally	Machinapally	11KV	Suryapet	10.00	12.45	02.45	E/L	Insulator flashover	No
3		Agamothkur	Bommakal	11KV	Miryalaguda	00.00	11.00	11.00	E/L	Heavy gale and wind	No
4		Molkapatnam	Molkapatnam	11KV	Miryalaguda	06.19	07.15	00.56	E/L	Heavy gale and wind	No
1	MDK	SOL	BMF	11KV	Sangareddy	13:05	14:20	1:15		Tree branche fallen on the line	No
1	RR N	Laxmapur	Laxmapur	11KV	Medchal	16:50	18:00	1:10		Lizard Fallen on 11KV Line at Laxmapur Village	No
2		GP Pally	Dulapally	11KV	Medchal	18.30	20.00	01.30		11KV Pole Damaged by Lorry at DRS School backside	No
1	RR E	NGRI	Scientist colony	11KV	Habsiguda	20:55	21:30	0:35		Cable failed at Blue Orched near Habsiguda Main Road	No