

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		3		3		3			
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1	2	2	2	2			
2	NLG	144	988	1	13		4		4			
3	MDK	107	933	2			1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	14	2	7	2	7	0	0	
	Grand Total	1082	6468	3	18	2	11	2	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Suryapet	Chandupatla	33KV	Huzurnagar	04.00	09.00	05.00	EL/OL	Due to 33KV Insulator Failed	Suryapet	-
1	MDK	Gummadidala	Gummadidala	33KV	Patancheru	14.45	16.30	01.45		B/D Due to Conductor Snapped	Gummadidala	-
2		Gummadidala	Dundigal	33KV	Patancheru	14.45	16.30	01.45		B/D Due to Conductor Snapped	Gummadidala	-

TSSPDCL - LMRC / Corporate office

Date: 14.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Nagasala	11KV	Jadcherla	08.20	10.12	01.52		Due to 11 KV Insulator failed Near Nagasala(V)	-
1	NLG	Pamanagundla	Yerasanigudem	11KV	Nalgonda	05.15	07.35	02.20	E/L	Tree branches fallen on 11KV line at Padadi Venkat Reddy Bavi	-
2		Reddygudem	Kukkadam	11KV	Suryapet	07.00	10.25	03.25	E/L	Conductor snapped	-
3		Thungathurthy	Ganugubanda	11KV	Suryapet	03.00	07.00	04.00	E/L	Insulator flasover	-
4		Jalalpuram	Jalalpuram	11KV	Suryapet	05.45	08.40	02.55	E/L	Disc flashover	-
5		Mamillagudem	Thummalapally	11KV	Huzurnagar	04.20	06.25	02.05	EL	Due to 11kv Insulator failure	-
6		Dirsincherla	Narasayagudem	11KV	Huzurnagar	06.00	09.00	03.00	EL	Due to 11Kv line cutted	
7		Burugadda	Gopalapuram	11KV	Huzurnagar	07.00	09.30	02.30	EL	Due to 11kv line snapped	
8		Kondamadugu	Nemaragommula	11KV	Bhongiri	02.00	06.00	04.00	EL/OL	1no's 11kv Pole Dammaged near Janaypally Village Line AB Swich Open near Kondamadugu Village	
9		Athmakur	Rahimkhanpet	11KV	Bhongiri	04.00	10.00	06.00	EL/OL	11kv Pin Insulator Failed near Pochamma Kunta Due to Hevay Gale & Wind	
10		Ambala	Parupally	11KV	Bhongiri	05.30	10.50	05.20	EL	11kv Line Snapped near Parupally Village	-
11		Ambala	Modubavigudem	11KV	Bhongiri	08.30	12.50	04.20	EL/OL	11kv 2no's Poles Dammaged	-
12		Veluvarthy	Sunkishala	11KV	Bhongiri	04.00	10.00	06.00	EL/OL	11kv Line Top plate Failed	-
13		Mothkur	Mothkur Rural	11KV	Bhongiri	06.00	09.30	03.30	EL/OL	phase to phase near Mothkur Village .Due to Hevay Gale & Wind	-
1	RR S	Kismathpur	Rock Church	11KV	RJNR	01.55	03.15	01.20	B/D	No Visible Fault Due to heavy rain and Gale , Wind	Kismathpur
2		Kattedan-I	Feeder-I	11KV	RJNR	16.00	17.10	01.10	B/D	11kv insulator Failed Nearr gouri plastic industries	Kattedan-I
3		Gaganpahad	Rajendranagar(V)	11KV	RJNR	02.10	04.05	01.55	B/D	No Visible Fault Due to heavy rain and Gale , Wind	Gaganpahad
1	RR E	Yapral	Yapral	11KV	Sainikpuri	01.10	03.00	01.50		Full Tree fallen on 11Kv line at Water Tank Yapral (AE/OP)	-