

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		3		3		1		
2	NLG	144	988	1	11	1	11	1	11			
3	MDK	107	933				1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>5</b>	<b>11</b>	<b>4</b>	<b>12</b>	<b>4</b>	<b>12</b>	<b>1</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>17</b>	<b>4</b>	<b>18</b>	<b>4</b>	<b>18</b>	<b>1</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 15.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Bijnapally	33KV	Nagarkurnool	17.14	19.04	01.50	O/I	33KV Vatterem Line Opened Supply Stood OK		NO
2		Nagarkurnool	Rakonda	33KV	Nagarkurnool	20.44	22.20	01.36	E/L	Opening of Kondareddypally Jumpers Supply Stood OK		NO
3		Shadnagar	Rayalaseema	33KV	Shadnagar	15.45	17.30	01.45	E/L&O/L	Tree fallen on the line near Rayalseema company		NO
4		Kalwakurthy	Sirsangandla	33KV	Nagarkurnool	15.18		08.42	E/L	Not Rectified Due to Limb Failed & Breaker Flash Over		NO
1	NLG	Miryalguda	Reddys Lab	33KV	Miryalguda	07.50	11.54	04.04	E/L	33Kv Conductor sanpped		-

TSSPDCL - LMRC / Corporate office

Date: 15.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Madgulapally	Kukkadam	11KV	Nalgonda	08.30	10.40	02.10	E/L	11 KV Line Jumper Cut	-
2		Bopparam	Palem	11KV	Nalgonda	09.20	11.56	02.36	E/L	11 KV Disc Failure	-
3		Pamanagundla	Errasanigudem	11KV	Nalgonda	07.40	09.10	01.30	E/L	HT/LT Lines Melt	-
4		Bommakal	Vemulapally	11KV	Miryalguda	00.00	12.40	12.40	E/L	Tree fallen	-
5		Dirsenpally	Miryala	11KV	Suryapet	11.30	14.00	13.40	E/L	11Kv Inaulator failed	-
6		Athmakur(S)	Athmakur(S)	11KV	Suryapet	08.00	09.15	14.40	E/L	HT/LT Line melt	-
7		Alingapuram	Raghavapuram	11KV	Huzurnagar	05.00	07.15	02.15	E/L	11Kv Conductor sanpped	-
8		Paladugu	Dathappagudem	11KV	Bhongir	10.50	11.50	01.00	E/L	11kv Ilne Snapped near Dathappagudem Village	-
9		Pamkunta	Singaram	11KV	Bhongir	12.00	16.40	04.40	E/L	11kv Pin Insulator Failed near Singaram Village	-
10		Pamkunta	Pamkunta	11KV	Bhongir	15.00	15.20	00.20	E/L	11kv Line Snapped near Pamkunta Village	-
11		Chada	Nancharipet	11KV	Bhongir	14.00	16.30	02.30	E/L	11kv Line Snapped near Sarvapally Village	-
1	RR N	Petbasheerabad	Satyam Enclave	11KV	Medchal	15.32	16.17	00.45		Tree Branches fallen on the 11KV Line at Pragma Tools Colony	-
2		Devarayamjal	Pothaipally	11KV	Medchal	16.55	18.00	01.05		11KV Brass Patti cut and replaced at Veluma Sangam FunctionHall, Yamjal	-
1	RR E	RGK	Kowkooor	11KV	Sainikpuri	19.30	20.10	00.40		Tree fallen on 11Kv line at Kowkooor Kallu Compound (LM Rajender)	-
2		Peerzathiguda	Uppal hills	11KV	Keesara	15.15	16.40	01.25		copper patti cut at Kuruma nagar	-
1	HYD S	Miralam	Ansari Road	11KV	Charminar	15.55	17.05	01.10	EL,OL	HT lines Twisted, Jumper cut & Brass Patti B/o at Ansari Road	-
1	HYD C	S.D Hosptial	Humayun Nagar	11KV	Mehdipatanam	15.57	17.00	01.03	EL,OL-Rph	Tree branches on lines at Meena Hospital	-