

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		9		9		9			
3	MDK	107	933	1		1		1				
4	SDPT			4	1	4	1	4	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	7	10	7	10	7	10	0	0	
	Grand Total	1082	6468	7	11	7	11	7	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.05.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Puttapad	Nancherla	33KV	Mahabubnagar	21.20	22.20	01.00	E/L	33KV Line Problem	Nancherla	No
2		Midjil	Velugomula	33KV	Jadcherla	17.15	00.05	06.50	E/L	8 Nos Failure insulator replacement	Velugomula	No
1	MDK	R.C.Puram	Ashok nagar	33KV	Patancheru	14:50	18:55	04.05		Jumper cut	Ashok nagar	No
1	SDPT	Mustyala	Mustyala	33KV	Husnabad	12:25	17:30	05.05		Jumper cut at 132KV SS	Mustyala	No
2		Mustyala	Dhoolmitta	33KV	Husnabad	12.25	17.30	05.05		Jumper cut at 132KV SS	Dhoolmitta	No
3		Mustyala	Komuravelly	33KV	Husnabad	12.25	17.30	05.05		Jumper cut at 132KV SS	Komuravelly	No
4		Mustyala	Tharigoppula	33KV	Husnabad	12.25	17.30	05.05		Jumper cut at 132KV SS	Tharigoppula	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Athmakur(s)	Athmakur(s) AGL	11KV	Suryapet	8:30	11:20	2:50	E/L	Disc failed	No
2		Dirincherla	Somaram	11KV	Huzurnagar	03.30	06.00	02.30	E/L	11 KV Line snapped	No
3		Dirincherla	Yallapuram	11KV	Huzurnagar	08.30	10.45	02.15	E/L	11 KV Jumper cut	No
4		Venkiryala	Jampally	11KV	Bhongir	02.40	12.00	09.20	E/L	11KV 1No. Pole Damaged	No
5		Pallerla	Pallerla	11KV	Bhongir	06.00	08.00	02.00	E/L	11KV Pin Insulator failed	No
6		Velmajala	Sitharampur	11KV	Bhongir	03.00	07.00	04.00	E/L	HT/LT & 11KV Jumper Cut	No
7		Rajupeta	Jonnagaddalagudem	11KV	Nalgonda	11.20	15.40	04.20	E/L	11KV line cut at Rangaiah AGL land	No
8		Baironibanda	B.Banda	11KV	Nalgonda	10.50	12.20	01.30	E/L	11KV Disc failed	No
9		Matoor	Lift	11KV	Miryalaguda	13:00	14:30	1:30	E/L	11KV Conductor snapped	No
1	SDPT	Gouravelly	Gouravelly Rural	11KV	Husnabad	0:00	6:50	6:50		Due to HT/LT	
1	HYD S	Falaknuma	Chatrinaka	11KV	Charminar	18.55	20.20	01.25	EL,OL-Bph	Sparking Line AB Switch at Chatrinaka & removed loads of 11KV Gowlipura fdr	No