

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988	1	14	1	14	1	14			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>23</b>	<b>2</b>	<b>23</b>	<b>2</b>	<b>23</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 27.05.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	17.03	19.15	02.12	E/L	Insulator Replacement	Machanpally	No
1	NLG	Shaligowraram	Akaram	33KV	Nalgonda	7:03	12:40	5:37	E/L	E-Ph Out Goining Jumper Cut	Akaram	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Kothur	11KV	Jadcherla	11.00	13.30	02.30		11 KV Insulator failed near Kothur Village	No
1	NLG	Edloor	Naregudem	11KV	Nalgonda	13:00	17:00	04.00	E/L	11KV line cut 2No.11Kv Line Insulator Fail	No
2		Narsing Batla	Chenugudem	11KV	Nalgonda	11.00	15.00	04.00	E/L	11KV Line insulator failed HT/LT Line cut	No
3		Devarakonda	Mynampally	11KV	Devarakonda	06.30	08.30	02.00	E/L	11KV Jumper Cut	No
4		Cherukupally	Cherukupally	11KV	Devarakonda	06.10	12.00	05.50	E/L	Pin binding dropped Thouched the V X Arms	No
5		Ghanapuram	G.B.Pally	11KV	Devarakonda	05.40	11.10	05.30	E/L	11Kv Jumper Cut	No
6		Ghanapuram	SLBC	11KV	Devarakonda	06.30	09.20	02.50	E/L	Tree fallen on 11KV line	No
7		Athmakur(s)	Athmakur(s) AGL	11KV	Suryapet	08.30	11.20	02.50	E/L	11KV Disc failed	No
8		Palakeedu	Sajapuram	11KV	Huzurnagar	07.40	10.00	02.20	E/L	11KV Jumper Cut	No
9		Alingapuram	Chennaipalem	11KV	Huzurnagar	07.00	10.00	03.00	E/L	1 Phase DTR Failed	No
10		Mukundapuram	Dacharam	11KV	Huzurnagar	06.50	09.00	02.10	E/L	11KV Line snapped	No
11		Ananthagiri	Shantinagar	11KV	Huzurnagar	10.45	12.45	02.00	E/L	11KV Line snapped	No
12		Peddathanda	Peddathanda	11KV	Bhongir	08.15	12.15	04.00	E/L	11KV Jumper Cut at Maisammakunta near Peddathanda (V)	No
13		Koyyalagudem	Koyyalagudem Agl	11KV	Choutuppal	05.10	10.07	04.57	E/L	Tree branchess fallen at Line near Koyyalagudem Village	No
14		Jai kesaram	Assonigudem	11KV	Choutuppal	9:22	13:25	04.03	O/L	11KV Line snapped near Assonigudem Village	No
1	RR N	Petbasheerabad	Vaishnavi Enclave	11KV	Medchal	10:20	11:40	01.20		11KV Pin Insulator failed at Vaishnavi Enclave	No
2		Devarayamjal	Kottapet	11KV	Medchal	14.50	17.35	02.45		Cross arm fallen on the 11KV Line at DMC	No
3		Kandalkoya	Saigeetha Asramam	11KV	Medchal	17.50	20.40	02.50		Tree fallen on the 11KV Line at Kandlakoya	No
1	RR E	St.No.08	Eggwood	11KV	Habsiguda	14:47	15:48	01.01		Bird fallen on 11KV line & line touched to 33KV Line near Madhu Engg. Company	No
2		Chengicherla	Kamela	11KV	Keesara	01.10	02.50	01.40		11KV Cable failed at Kamela T/F	No
3		P&T Colony	Budda Nagar	11KV	Keesara	10.30	11.15	00.45		Line patrolling but no visible fault	No
1	HYD C	Amerpet	Play Ground	11KV	Azamabad	01.23	04.10	02.47	OL	Faulty loads of 11KV Babu Nagar feeder	No
2		Amerpet	Play Ground	11KV	Azamabad	04.40	06.45	02.05	OL	Over load (Plug setting changed at SS)	No