

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT				11		11		11			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>17</b>	<b>0</b>	<b>17</b>	<b>0</b>	<b>17</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>20</b>	<b>0</b>	<b>20</b>	<b>0</b>	<b>20</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 31.05.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL					NIL		-
2	NLG				NIL					NIL		-
3	MDK				NIL					NIL		-
4	SDPT				NIL					NIL		-
5	RR S				NIL					NIL		-
6	RR E				NIL					NIL		-
7	RR N				NIL					NIL		-
8	HYD				NIL					NIL		-

## TSSPDCL - LMRC / Corporate office

Date: 31.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Gaddipaly	Ponugodu	11kv	Huzurnagar	10.00	13.00	03.00	E/L	Lt Pole hitted by tractor	-
2		Gaddipaly	Gaddipaly	11kv	Huzurnagar	12.15	13.20	01.05	E/L	Agl 11Kv jumper cut	-
3		Gondriyala	Gondriyala-2	11kv	Huzurnagar	09.00	12.00	03.00	E/L	Tree branch fall on 11kv line	-
4		Athmakur(S)	Gottimukkula gudem	11kv	Suryapet	05.50	08.45	02.55	E/L	11Kv Disc Flashover	-
5		Pamanagundla	Yerasanigudem	11kv	Nalgonda	07.37	13.55	06.18	E/L	11 KV Tree Fallen on the Line	-
6		Pamukunta	Singaram	11kv	Bhongir	04.00	09.30	05.30	E/L	11Kv Disc Failed at Durgamma Temple back side Near Singaram (V)	-
1	SDPT	Guggilla	Thimmaipally	11kv	Husnabad	04.00	11.40	07.40		Breakdown	-
2		Chityal	Dommata	11kv	Husnabad	07.05	07.30	00.25		Breakdown	
3		Guruvannapet	Guruvannapet	11kv	Husnabad	00.00	06.00	06.00		Breakdown	
4		Akkannapet	Pakilnayak Thanda	11kv	Husnabad	15.00	23.54	08.06		Breakdown	
5		Dharmaram	Dharmaram Town	11kv	Husnabad	00.00	05.00	05.00		Breakdown	
6		Dharmaram	Nandaram	11kv	Husnabad	00.00	05.00	05.00		Breakdown	
7		Dharmaram	Nandaram	11kv	Husnabad	06.35	10.25	03.50		Breakdown	-
8		Dharmaram	Potharam(J)	11kv	Husnabad	00.00	03.00	03.00		Breakdown	-
9		Husnabad	Pandilla	11kv	Husnabad	00.00	09.00	09.00		Breakdown	-
10		Husnabad-2	Malapally	11kv	Husnabad	00.00	06.25	06.25		Breakdown	-
11		Rebarthy	Ladnoor	11kv	Husnabad	00.00	07.10	07.10		Breakdown	-
1	RR E	Chengicherla	My Villas	11kv	Keesara	05.12	07.12	02.00		11KV Jumper cut at My Villas Backside	-
1	HYD N	Macha Bollarum	Radha Sath Sang	11KV	Bowenpally	14.20	16.10	01.50	All Indication	Faulty 2No. DTR's at Radha Sathsang	
1	HYD S	C.R.P.F	C-Block	11KV	Charminar	07.52	10.20	02.28	EL,OL	Cable fault at Harmin Masjid	-